

Part Number Update



Bulletin No: PNU-130-000

Effective Date: December 5, 2008 Cancels: N/A

Page: 1 of 1

Subject: Discontinuance of Bendix® SD-3™ and DD-3™ Actuators

Bendix Spicer Foundation Brake LLC is discontinuing the availability of the SD-3™ and DD-3™ actuators and service replacement components. The time line below outlines the phase-out process.

Prior to December 5, 2008: Orders will be accepted until December 5, 2008 or until current inventories are depleted. All Bendix Services will be available.

After December 5, 2008: All Bendix Technical and Customer Support will continue to be available for the listed products until December 31, 2009. Orders will be processed for items in inventory.

After December 31, 2009: Bendix Technical Support (SWAT) will be available in support of the Bendix® product in the field.

Actuator Type	OE Piece Numbers		Service Piece Numbers				
DD-3™	284994	287475	284363	284998	285024	287329	800304
	284996	287479	284364	285006	285027	287442	800549
	285009	287557	284656	285008	286167	287460	800550
	286503	5002789	284993	285009N	287185	287465	
	287194	5002790	284994N	285018	287186	287475N	
	287448	5005040	284995	285021	287326	287479N	
SD-3™			284997	285022	287328	800303	
	286495	286496	284912	285069	285073	286496N	
			285068	285072	286495N		

DD-3™ Service Parts

Service Piece Number	Description
243342	Push Rod
247022	Service Pressure Plate
248101	Push Rod
249250	Non Pressure Plate
279726	Clamp Ring Assembly
279727	Clamp Ring Assembly
285116	Non Pressure Plate Complete
285117	Non Pressure Plate Complete
287174	Auxiliary Pressure Plate Complete
290943	Service Pressure Plate
291372	Service Pressure Plate