## Part Number Update

Bulletin No: PNU-166-A

Effective Date: July 27, 2012

Cancels: PNU-166, dated July 13, 2012

Subject: Bendix® ATR-6™ Traction Relay Valve Supersession Notice

Beginning immediately, the following Bendix<sup>®</sup> ATR-6<sup>™</sup> Traction Relay Valves will have the following direct service replacement numbers. Please use the listed replacement part number for all orders.

Original Bendix® Part Number	New Bendix® Part Number	Crack Pressure	Availability
803009	K070954	5.5 psi	Available August 2012
803010	K072293	5.5 psi	Available Now
803119	K070951		
803120	K070975	5.5 psi	Available August 2012
803121	K078219	4.0 psi	Available Now
803122	K070976	4.0 noi	Available August 2012
803169	K078421	4.0 psi	
803170	K078420	5.5 psi	Available Now
K023889	K072311	4.0 psi	
K023890	K072312	5.5 psi	Available August 2012
K023891	K072318	4.0 psi	Available Now
K035620	K070958	4.0 psi	Available Now
K035621	K070959	5.5 psi	Available August 2012
K035622	K070962	4.0 psi	Available Now
K037238	K070956		Available August 2012
K041117	K070964		
K042710	K072339	4.0 psi	Available Now
K042711	K072340	5.5 psi	Available August 2012
K042712	K072341		
K042713	K072342	4.0 psi	
K042974	K070965		
K042975	K070966		
K043289	K072343		
K045413	K070963	4.0 psi	Available Now
K047838	K072344	4.0 psi	Available August 2012
K048107	K070955	5.5 psi	
K048672	K070974	4.0 psi	
K048673	K070973	7.5 psi	
K049444	K072345	4.0 psi	Available Now
K057084	K070967	5.5 psi	Available August 2012
K070952	K078219	4.0 psi	Available Now
K070953	K078420	5.5 psi	



Page: 1 of 1

BENDIX® ATR-6™ ANTILOCK TRACTION RELAY VALVE.

## Repair Kit:

Use Kit part number 102802N in cases where there is leakage at the exhaust port, and where the valve itself is not cracked or damaged.